


400 amp Meter Base

Correct Wiring Diagram for Jasper County REMC Service



Meter base ground must be unbroken from ground rod to ground connection in base. Ground wire must be in 1/2" thin wall conduit or 1/2" grey electrical PVC. Connect #4 copper to ground rod with an Acorn ground clamp.